

Amfori Photo report			
Monitoring ID	23-0201629	Site amfori ID	156-048182-001
Monitored Party	Jiangsu Sun Outdoor Products Factory		
Auditor	Wylie Wang	Audit Date	July 19, 2023




## Photo Form

		
Factory Name	Factory Overview	Production building




		
Factory Address	First aid kit	Exit sign and emergency light

		
Fire Hydrant	Fire extinguishers	Fire alarm switch

Amfori Photo report			
Monitoring ID	23-0201629	Site amfori ID	156-048182-001
Monitored Party	Jiangsu Sun Outdoor Products Factory		
Auditor	Wylie Wang	Audit Date	July 19, 2023

		
Raw material warehouse	Finished goods area	Fire sprinkler system

		
Drinkable water area	BSCI Code display	Evacuation Plan

		
Printing section	Sewing section	Toilet

Amfori Photo report			
Monitoring ID	23-0201629	Site amfori ID	156-048182-001
Monitored Party	Jiangsu Sun Outdoor Products Factory		
Auditor	Wylie Wang	Audit Date	July 19, 2023



Fire Hydrant testing



Ironing section



Suggestion box



Packing section



Digital printing section



Cutting section



Metal glove



Inside of dormitory



Attendance machine



Canteen




Dormitory building



Elevator

Amfori Photo report			
Monitoring ID	23-0201629	Site amfori ID	156-048182-001
Monitored Party	Jiangsu Sun Outdoor Products Factory		
Auditor	Wylie Wang	Audit Date	July 19, 2023

NC photo

		
<p>NC-7.6 printing worker without proper mask</p>	<p>NC-7.7 partial chemical containers without secondary container</p>	<p>NC-7.22 no privacy door in toilet</p>
		
<p>NC-7.17 sewing machine without needle guard</p>	<p>Nil</p>	<p>Nil</p>